



Department of Environmental Quality Division of Solid and Hazardous Waste

Michael O. Leavitt Governor Dianne R. Nielson, Ph.D. Executive Director Dennis R. Downs Director

288 North 1460 West P.O. Box 144880 Salt Lake City, Utah 84114-4880 (801) 538-6170 (801) 538-6715 Fax (801) 536-4414 T.D.D. www.deq.utah.gov

July10, 2003

RECEIVED
JUL 1 1 2003

DIV. OF OIL, GAS & MINING

Bruce A. Cason Plant Manager U.S. Gypsum P.O. Box 570160 Sigurd, Utah 84657

Subject:

Landfill Inspection - Plant Waste/Recycle Pile Status

Dear Mr. Cason:

On May 20, 2003, Mr. Jeff Emmons of our agency and Mr. John Vercoe with the Central Utah Public Health Department conducted an inspection of the U.S. Gypsum Jumbo Landfill. Mr. Kyle Morris, Quarry/Mill Manager, accompanied them on the inspection. The purpose of the inspection was to determine compliance with the *Utah Solid Waste Permitting and Management Rules* (Rules) and conditions of the landfill permit. In addition, the status of the gypsum waste/recycling pile next to the plant was reviewed. Enclosed is a copy of the inspection report and the current rules.

The landfill appeared to be well operated, maintained, and in compliance with the rules and the landfill permit. An examination of the landfill records was conducted at the plant office. All the required documentation and records were present, well organized, and readily available.

Following the inspection of the landfill, a tour was conducted of the plant waste/recycle pile, located adjacent to the plant. To ensure protection of human health and the environment, some of the management practices regarding the pile are regulated by the rules. The specific rules, which apply to the pile, depend upon how the pile is managed. For example, if the pile of material is intended for recycling, Section R315-312 of the Rules may apply. If the pile is being managed as a disposal site, the site must comply with the Class IIIb industrial landfill rule requirements and a disposal permit is required. If the site is used as temporary storage prior to disposal at another location, Section R315-314 of the Rules may apply.

U.S. Gypsum must define the management objective for the material pile and submit a detailed management plan, to the Executive Secretary of the Utah Solid & Hazardous Waste Control Board by December 31, 2003. Application of the appropriate rules will be based on the review of the management plan.

Please feel free to contact Jeff Emmons at 801-538-6748 to discuss the details of the Rule requirements, and the preparation of the required documents.

In summary, the Division appreciates the effort required to operate the Jumbo Landfill within the requirements of the rules and the Permit. We look forward to working with U.S. Gypsum in the development of the management plan for the plant waste/recycle pile.

Sincerely,

Dennis R. Downs, Executive Secretary

Utah Solid and Hazardous Waste Control Board

DRD/je/kk

Enclosures

c: Robert Resendes, Director, Central Utah Public Health Dept.

Roger Foisy, DEQ Central Utah District Engineer

Lynn Kunzler, DOGM

Kyle Morris, U.S. Gypsum Company

Frank May, U.S. Gypsum Company

SOLID WASTE FACILITY INSPECTION REPORT UTAH DIVISION OF SOLID & HAZARDOUS WASTE

Facility Name United States Gypsum Company	County Sevier
Location Sigurd Utah Plant- Approximately 3 miles north east of plant on quarry road. Inspection Date 5-20-03 Began/Ended 9:00 am- 11:30 am Operating Hours	
REASON FOR INSPECTION	Operating Hours
Routine Follow up Complaint Closure/Post	Closure Other
Weather Conditions Clear sky, calm winds	Area(s) Inspected Jumbo landfill and plant waste/recycle pile
Facility Representative(s) Accompanying the Inspection Kyle Morris- Quarry / Mill Manager	
	eff Emmons- DSHW, John Vercoe- Central Utah Public Health Dept.
FOLLOW UP INSPECTION NEEDED Yes No 🛛	Recommended Follow Up Period
(X - indicates items reviewed – Comments on next page/s)	
1. FACILITY / OPERATIONAL CONTROLS	8. PLANS / PROGRAMS ON FILE
☐ Litter ☐ Roads Maintained	☐ Contingency ☐ Operating / Maintenance
☐ Weighing Loads ☐ Vectors ☐ Communications ☐ Recycling Provided to	☐ Inspection ☐ Removal-Stored Waste
Communications Recycling Provided to Public	☐ Facility Site Plan ☐ Leachate Control ☐ Closure / Post Closure ☐ Deviation from Plans
	☐ Closure / Post Closure ☐ Deviation from Plans ☐ Methane Monitoring ☐ Training Programs
☐ Tipping / Insp. Area ☐ Scavenging Control	Groundwater Monitor Disposal Management
No Open Burning	Disease Vectors / Rodent Fire Protection &
	Control Prevention
	Permit & Plan of Operation
2. SIGNS REQUIRED / PROPERLY POSTED Operating Days / Hrs. Other Info as Required	RECORDS / REPORTS / RESULTS MAINTAINED 9. INSPECTION RECORDS
Fires Prohibited Directions & Procedures	Random Inspect. Rept Gas Monitoring System
Emergency Numbers Scavenging Prohibited	☐ Surface Drainage Control ☐ Daily Records Kept ☐ Leachate Collection ☐ Weight or Volumes
List of Unacceptable Materials	☐ Leachate Collection ☐ Weight or Volumes System
	☐ Intermediate Cover ☐ Types of Waste Received
	Final Cover Number of Vehicles
3. OPERATOR / REPRESENTATIVE / EMPLOYEES	Self Inspection (Quarterly) Reports
☐ On-site while open ☐ Employees Trained	Records inspection.
	10. MONITORING / SAMPLING / ANALYSIS RECORDS
4. MONITORING	☐ Unauthorized Waste ☐ Methane Taken Quarterly
☐ Methane ☐ Random Inspections	Analyzed
☐ Leachate ☐ Proper Equip / Test Used	Contaminated Waste / Leachate Sampling &
Ground Water Unauthorized Waste	Soil Analyzed Treatment Ground Water Sampling Results
Analyzed Frequency Maintained	Ordina Water Sampling Results
	and the second s
5. DRAINAGE / EROSION	11. SPECIAL WASTE RECORDS
Water Run-on	Lab Analysis Results Manifests
	☐ Treatment Certification ☐ Paint Filter Test Results ☐ Remediation Documentation
6. PROPER STORAGE / ISOLATION / DISPOSAL	
Special Waste Batteries	12. SPECIAL PERMIT REQUIREMENTS
Hazardous Waste Infectious Waste	
☐ Tires ☐ Dead Animals ☐ Asbestos ☐ Bulky Waste	
Contaminated Soil Ash	
Petroleum Waste Sludge	13. OTHER ITEMS
	Digital Photographs #1237 thru 1246 are enclosed.
7. COVER	Permit wording
Daily Applied Intermediate Applied	
Final cover Stabilized Vegetation	
Cover as needed	Ц

SOLID WASTE FACILITY INSPECTION PEPORT

Date:5/20/2003 Facility Name: United States Gypsum Company Detail No. Item The waste disposed at the landfill consist of off spec. wall board, wall board pieces, and wall board paper. Litter Waste stream is not prone to creating litter. Landfill site was clean of litter. No waste was observed outside landfill boundaries. Waste is unlikely to cause a fire threat. No evidence of any burning onsite. Open Burning Mininmized Working Management of working face was discussed onsite. Operation is conducted to minimize the working face. Face Roads Maintained The quarry haul road and onsite road is in good shape. Waste stream will limit production of vectors. Waste is dry, is not a food source, and cover frequency prevents Vectors harborage for vectors. Gate is locked except when quarry is operating. Haul road traffic monitors landfill to ensure unauthorized entry Access Control is prohibited. Access is controlled by gate fencing and natural topography. 1 Access to site is limited to US Gypsum personnel. Scavenging is prohibited. Scavenging Control 1 Gate and Fencing Landfill gate is operational and is locked and unlocked at the beginning and end of day shift. Fencing is in good shape. 3 Landfill accepts only waste from the US Gypsum plant waste and is delivered by plant personnel. Onsite Employee 4 Random Inspeciton Permit requires general inspection of each load and any suspicious loads will be inspected. 5 Run on control consist of berms and ditches and apprear to be effective. Water Runon Permit requires the waste to be covered at least every six months with a minimum of 3 inches of shale or earthen Cover material. Site has received required covered. 8 Permit & Plan of The landfill permit and application are maintain at plant office, are readily accessible, and well maintained... Operation 9 Records Inspection Landfill inspection included review of all records keeping requirements included in the permit. All recordkeeping requirements are being met. 13 **Digital Photos** Digital photographs taken during the inspection are included. 13 Permit Wording An error was made with the January 16, 2003 mailing to US Gypsum of the approved permit. The inspection revealed that the draft permit was mailed instead of the final permit. Enclosed in the final permit.

Division of S&HW Inspector Name:

Jeff Emmons

Date:

6/9/03




Photo #1237- US Gyspum Jumbo Landfill taken at 9:02 am 5-20-03 Photo looking west.




Photo #1238- US Gypsum Landfill taken at 9:03 am 5-20-03 Photo shows working face with cover soil applied



Photo # 1239 US Gypsum Jumbo Landfill taken at 9:06am 5-20-03 Close up of waste.



Photo #1240- US Gypsum Jumbo Landfill taken at 9:06am 5-20-03 Close up of waste



Photo #1241- US Gypsum Plant Waste / Recycling Pile taken at 9:25 am 5-20-03 Photo taken from top of pile looking east to Sevier River.




Photo # 1242- US Gypsum Plant Waste / Recycle Pile taken 9:26 am 5-20-03. Photo taken on top of pile looking south




Photo # 1243- US Gypsum Plant Waste / Recycle Pile taken 9:26 am 5-20-03. Photo taken of haul road near the top of pile.




Photo #1244- US Gypsum Plant Waste / Recycle Pile taken 9:31am 5-20-03. Photo taken of material on top of pile. Looking South- Note Georgia Pacific plant in background.



Photo # 1245- US Gypsum Plant Waste / Recycle Pile taken at 9:33am 5-20-03. Photo taken from top of pile looking north.




Photo # 1246- US Gypsum Plant Waste / Recycle Pile taken at 9:33am 5-20-03. Photo taken from top of pile looking south toward US Gypsum Plant.

TN200301634.doc